

MEMORANDUM

May 6, 2020

TO: Reclamation District No. 2026

FROM: Nathan Hershey

SUBJECT: May 2020 Engineer's Report

Described below are the engineering items to be discussed at your May 6, 2020 meeting.

Subventions 2018-19 – The District submitted an application for participation in the Program in the amount of \$400,000. \$12 million has been approved for Program funding for FY 2018-19, consistent with recent previous years. The District's final claim was been submitted in the amount of \$209,466.23. DWR and CDFW have performed their annual inspection and the claim is currently being processed.

Subventions 2019-20 – The District submitted an application for participation in the Program in the amount of \$500,000. DWR has lowered the Program funding amount to \$10 million for FY 2019-20.

Subventions 2020-21 – Applications for participation in the Program were due April 1. The District submitted an application in the amount of \$2,395,000. We have received notice from DWR that \$12,000,000 is being committed to the Program for FY 2020-21.

Annual Maintenance – Attached are the current maintenance items we are tracking. We recommend reviewing the waterside slope conditions via drone and performing any routine maintenance required prior to the flood season.

Five Year Plan – Work on the Five-Year Plan is currently in progress. A draft of the plan has been distributed via email. The Plan must be complete by the end of 2020.

DWR Emergency Response Grant Update – We are still waiting to see the final version of the Local Flood Safety Plan.

SB 88 – Work under Phase 2 of the measurement experiment (work plan for 2019 through February 2020) has been completed. All the data collected during this period has been reviewed and analyzed. MBK has prepared a draft report to update last year's experiment summary report. This draft was provided to MWD for final review and will be finalized as soon as comments are received. Work under Phase 3 of the measurement experiment (February 2020 through February 2021) is underway, as outlined in the approved Request for Additional Time.

Phase 3 efforts primarily involve installing 8 additional flange magnetic meters on the water side of the highest use siphons, with at least one flow meter on each island. MBK conducted site visits to each of the proposed sites during April to check installation locations and pipe conditions. All proposed sites will include telemetry equipment, with the intent to post data to the Reclamation District websites for each island. MBK has obtained quotes for equipment and installation costs, which will be provided to MWD for review soon.

RD 2026 Engineer's Report

The Delta Measurement Experiment Consortium has not yet scheduled its next meeting and MBK has not received any updates on the status of the Open ET beta testing.

Reclamation District No. 2026 Webb Tract Issue Tracking Summary 5/1/2020

IssuelD	Priority	Report Date	Reporter	Location	Issue Type	Description	Action	Field Notes
						Pump station platform		Dino to investigate and
						pile appears to have		repair; Schedule TBD. See
3	Medium	10/4/2016	Jaime Barajas	Station 614	Broken Equipment	buckled.	Repair	photos.
								Jaime to monitor. On
								3/22/17 District forces
								coretrenched levee and
						Boil located near pump		found no cause for
19	Medium	2/1/2017	Jaime Barajas	Station 614	Boil	station	Investigate	seepage.
						Possible small crack		
						between WS crown and		
50	Low	7/21/2017	Russ Ryan	Station 180	Crack	AB splash berm	Monitor	
								Investigate problem; This
								has been a long-term
								issue. 6/9/18 Photos
						Seepage under		received from Jaime; MBK
				Station 164+60		discharge pipes.		investigating options for
61	Medium	1/19/2018	Ralph Heringer	False River Pump	Seepage	Ongoing problem.	Monitor	remediation
						Seepage berm		
						construction complete.		
						RD forces placed 6,026		
						cy of material.		
61.1		6/10/2019	Nate Hershey			Continue to monitor.		
						Approx. 200ft of rip rap		
						sloughing		
69	Medium	7/10/2018	Andrew Reece	Station 408	Sloughing		Monitor	